Dometic

SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen


RM 7211/71/75/91/95, RM 7361/65/71/91/95, RM 7401/05, RM 7501/41/45/51/55, RM 7601/05/51/55, RM 7801/05/51/55

How to handle with broken axes on the MES or AES electronics


It might happen that the axes of operating knobs on the electronics could break. A broken axis should be replaced by a new axis.


Exchanging the electronic board is not necessary.

The following pictures show how to remove menaining pieces in the potentiometer.









Publication-No.: 599 5302-59 en / Service 2007.07.19 BO / KV

COOLING Caravan 3110